






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Αναλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, GN, ...

Pos.	Part No.
1	A 963 131 NU
2	A 963 132 NU
3	A 963 146 NU
4	A 960 890 NU
5	A 960 891 NU
6	A 960 706 NU
7	A 963 443 NU
8	A 960 500 NU
9	A 960 893 XX
10	A 860 902 XX
11	A 860 897 NU
12	A 861 409 XX
	A 861 410 XX
13	A 860 901 XX
14	A 861 408 XX
15	A 960 704 NU
	A 962 476 NU
16	A 6677 XX



A 7035..  
 A 7034..



Ideal Standard

**CONNECT AIR**  
 A 7034 .. A 7035 ..



1120 / A 868 373  
 Made in Germany










Ideal Standard International NV  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)





Pressure Gauge 0,3 MPa 3 bar	Thermometer 50°C 65°C 81°C	Snowflake 16°C	0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
			49,5	49,5	48	46	42,5	41	37	33,5	31	28
			65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
			81	81	78,5	73	69	63,5	56	49	42,5	36



Pressure Gauge P	bar	Pressure Gauge MAX. 10 0,5	Pressure Gauge 5 1	Thumbs up icon	Water Spray Q (3 bar)
Thermometer T	°C	Thermometer MAX. 80	Thermometer 65 40	Thumbs up icon	l/min 23