






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi


Pos.	Part No.
1	A 861 382 AA
2	A 861 371 NU
3	A 861 373 NU
4	A 861 245 NU
5	A 861 374 NU
6	A 861 372 NU
7	A 960 914 AA
8	A 7215 AA
9	A 861 816 AA




Ideal Standard








**CERATHERM T50**  
 A 7214 ..

0724 / A 868 552  
 Made in Germany



Ideal Standard International NV  
 Corporate Village – Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium  
<https://www.idealstandard.com>





	P	bar					Q (3 bar)
			0,5	1			
	T	°C					I/min
							22